

HO CHIEN ENTERPRISE CO., LTD.Report No.: CE/2004/C1994ANO. 6, LANE 130, SEC. 1, KUANG FU RD., SANDate: 2004/12/21CHUNG CITY, TAIPEI HSIEN 241, TAIWAN, R.O.C.Page: 1 of 2

The following merchandise was (were) submitted and identified by the client as :

<u>Type of Product</u>	:	1. COPPER ALLOY (6m/m) 2. COPPER ALLOY-Tin (6m/m)
Sample Received	:	2004/12/10
<u>Testing Date</u>	:	2004/12/10 TO 2004/12/21

<u>Test Result</u>

PART NAME NO.1	:	GOLDEN COLORED METAL(C1994) (PLEASE REFER TO THE PHOTO ATTACHED)
PART NAME NO 2	•	SILVER COLORED METAL(C1995) (PLEASE REFER TO THE PHOTO

PART NAME NO.2 : SILVER COLORED METAL(C1995) (PLEASE REFER TO THE PHOTO ATTACHED)

				Result				
Test Item (s):	Unit	Method	MDL	No.1	No.2			
Chromium VI (Cr+6)	ppm	As per US EPA 7196A and US EPA 3060A.	2	N.D.	N.D.			
Cadmium (Cd)	ppm	ICP-AES after as per EN 1122, method B:2001 or other acid digestion.	2	N.D.	N.D.			
Mercury (Hg)	ppm	ICP-AES after as per US EPA 3052 or other acid digestion.	2	N.D.	N.D.			
Lead (Pb)	ppm	ICP-AES after as per US EPA 3050B or other acid digestion.		24501.7	23249.1			

- NOTE : (1) N.D. = Not detected (<MDL)
 - (2) ppm = mg/kg
 - (3) MDL = Method Detection Limit

Operation Manager Signed for and on behalf of SGS TAIWAN LTD.

The content of this PDF file is in accordance with the original issued reports for reference only. This Test Report cannot be reproduced, except in full, without prior written permission of the Company



HO CHIEN ENTERPRISE CO., LTD.Report No.: CE/2004/C1994ANO. 6, LANE 130, SEC. 1, KUANG FU RD., SANDate: 2004/12/21CHUNG CITY, TAIPEI HSIEN 241, TAIWAN, R.O.C.Page: 2 of 2





The content of this PDF file is in accordance with the original issued reports for reference only. This Test Report cannot be reproduced, except in full, without prior written permission of the Company